

## Service Bulletin SB-0005

RE: Mechanical Seal Sand Cannon - For serial #'s 4130-4213

Date: 08/08/24

This Service Bulletin is to announce the addition of grease vent hole to the Trelleborg outer housing. This Vent will eliminate the build up of pressure inside the seal cavity.

Drill new grease vent hole on the bottom side opposite existing tapped grease fitting hole. Drill hole through to center cavity.

